Oil Field Environmental Incident Summary

Incident: 20150902161818 **Date/Time of Notice:** 09/02/2015 16:18 Responsible Party: RIM OPERATING, INC. Well Operator: RIM OPERATING, INC. Well Name: HUERFANO 11-23H Field Name: LAKESIDE Well File #: 17095 Date Incident: 9/2/2015 Time Incident: 08:00 Facility ID Number: **BURKE** County: **Twp:** 163 **Rng:** 89 Sec: 23 Qtr: **Location Description:** Submitted By: Liz Ortiz Received By: Contact Person: Ken Read **5 INVERNESS DRIVE EAST** ENGLEWOOD, CO 80112 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** 1 Mile Distance Nearest Water Well: 1 Mile Type of Incident Equipment Failure Release Contained in Dike Yes - Within Dike Reported to NRC: No **Spilled** Units Recovered Units Followup **Units** Oil **Barrels** 50 **Barrels Brine** 50 Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: unknown

Tuesday, September 15, 2015

Areal Extent:

n/a

Potential Environmental Impacts:

none

Action Taken or Planned:

Vac truck sucked up all of the water and disposed

Wastes Disposal Location: Steamboat 24-33 salt water disposal well

Agencies Involved:

Updates

Date: 9/2/2015 Status: Reviewed; O&G Lead Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.